
PRODUCT DATA

6311,6315

SCAT Wax & Grease Remover

DESCRIPTION:

SCAT is a specially formulated solvent blend for lifting and removing wax, silicone, grease and oil from surfaces to be painted. SCAT also provides a light etching action to improve paint adhesion. Used primarily as a pre-paint cleaner and conditioner to remove wax and silicone, SCAT leaves no residue on the surface.

TECHNICAL DATA:

APPEARANCE: Clear Liquid
SOLVENTS: Aliphatic and Aromatic Hydrocarbons
V.O.C. CONTENT: 6.48#/gal (777 g/l)

APPLICATION:

SCAT must be applied before sanding is done to prevent silicone or wax from being worked into the surface. Saturate a clean cloth with SCAT. Work small areas rubbing briskly. Wipe off immediately with a clean, dry cloth. Change cloths frequently to prevent spreading of contamination. Heavy coats may require two applications. Final application should be made in one direction only.

COMPETITION:

DuPont Prepsol #3919-S
R.M. Pre-Kleano #900
PPG Acryl Clean #DX330

The information contained on this data sheet is believed to be accurate at the time of printing. However, regulations governing V.O.C. levels are subject to change from time to time. Please consult with your local regulatory office for the latest regulations.

SEE REVERSE SIDE FOR APPLICATION INSTRUCTIONS

(Refer to Material Safety Data Sheet for proper handling of products listed in this bulletin).

PACKAGE SIZE:

#6311 SCAT Wax & Grease Remover, Gallon, 2/case

DISCLAIMER: The technical information and suggestions for use have been compiled for your guidance and usage. Such information is based on Transtar Autobody Technologies experience and research and is believed to be reliable. As Transtar has no control over conditions in which the product is used, stored, or otherwise handled, the above information does not constitute a warranty. Buyers must assume responsibility for the suitability of the product for their purposes.

